



*Cofe*

PATENT

I hereby certify that this correspondence is being deposited  
with the United States Postal Service as first class mail in  
an envelope addressed to Mail Stop Certificate Of Correction  
Branch, Commissioner For Patents, P. O. Box 1450,  
Alexandria, VA 22313-1450  
on May 8, 2006

*Wayne L. Jacobs* Reg. 35,553

Date

*May 8, 2006*

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number:	6,922,877	<b>Certificate</b>
Issued:	August 2, 2005	MAY 15 2006
Serial Number:	09/878,743	of Correction
Filed:	June 11, 2001	
Group Art Unit:	1732	
Examiner:	Mary Lynn F. Theisen	
Applicant:	John Linville, Donald R. Maier and Patrick M. Saaf	
Title:	CASKET LID AND METHOD OF MAKING SAME	

Cincinnati, Ohio 45202                    May 8, 2006

Mail Stop Certificate of Corrections Branch  
Commissioner for Patents  
P. O. Box 1450  
Alexandria, VA 22313-1450

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT**  
**FOR PTO MISTAKE (37 C.F.R. §1.322(a))**

Attached in duplicate is Form PTO-SB/44 with at least one copy being  
suitable for printing.

The following is the page and line number where the error occurs in the  
application file:

*MAY 15 2006*

January 4, 2002, Information Disclosure Statement, Form PTO-1449,  
page 3, entry 4, reads -- 3,729,786; --, not "3,729,785".

March 7, 2003 Response Under 37 C.F.R. §1.111, Claim 24, page 4, line  
10, reads: -- with said wood grain pattern formed in said crown on the other side of the --  
, not "with said wood grain pattern formed in said crown on the other side or the".

Specification, Claim 27, page 33, line 10, reads: -- continuous with said  
wood grain pattern formed in said --, not "continuous with said wood grain pattern  
fanned in said".

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By:

Wayne L. Jacobs  
Reg. No. 85,553

2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202

Phone: (513) 241-2324  
Fax: (513) 421-7269

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 6,922,877

APPLICATION NO.: 09/878,743

ISSUE DATE : 08/02/05

INVENTOR(S) : John E. Linville, Donald R. Maier and Patrick M. Saaf

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, Page 2, line 16, reads: "3,729,785 A 5/1973 Walding" when it should read: --3,729,786 A 5/1973 Walding --.

Column 7, Claim 1, line 45, reads: "said crown on the other side or the longitudinal axis of" when it should read: -- said crown on the other side of the longitudinal axis of --.

Column 8, Claim 4, line 20, reads: "grain pattern fanned in said crown on the other side of the" when it should read: -- grain pattern formed in said crown on the other side of the --.

**MAILING ADDRESS OF SENDER (Please do not use customer number below):**

Wayne L. Jacobs  
WOOD, HERRON & EVANS, L.L.P.  
2700 CAREW TOWER, 441 VINE STREET, CINCINNATI, OH 45202

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

2006

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 6,922,877

APPLICATION NO.: 09/878,743

ISSUE DATE : 08/02/05

INVENTOR(S) : John E. Linville, Donald R. Maier and Patrick M. Saaf

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, Page 2, line 16, reads: "3,729,785 A 5/1973 Walding" when it should read: --3,729,786 A 5/1973 Walding --.

Column 7, Claim 1, line 45, reads: "said crown on the other side or the longitudinal axis of" when it should read: -- said crown on the other side of the longitudinal axis of --.

Column 8, Claim 4, line 20, reads: "grain pattern fanned in said crown on the other side of the" when it should read: -- grain pattern formed in said crown on the other side of the --.

**MAILING ADDRESS OF SENDER (Please do not use customer number below):**

Wayne L. Jacobs  
WOOD, HERRON & EVANS, L.L.P.  
2700 CAREW TOWER, 441 VINE STREET, CINCINNATI, OH 45202

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

... 2006